



2647 Gateway Road, Suite #105-300, Carlsbad, CA 92009 - Ph (760) 683-5200

PROPOSAL ***DSA INSPECTION SERVICES***

September 17, 2018

Calexico Unified School District
901 Andrade Avenue
Calexico, CA 92231

Attention: Mr. Jeremy Nielsen, Director- Maintenance & Operations
RE: In-Plant Inspection Proposal
Project: Calexico High School

I am respectfully submitting my proposal for In-Plant inspection services relating to your relocatable buildings that will be manufactured at Silver Creek International in Perris, CA.

DSA IN-PLANT INSPECTION SERVICE										
PLANT MANUFACTURE: SCI #11165										
<table><thead><tr><th><u>No. & Size of Buildings</u></th><th><u>Inspection Rate</u></th></tr></thead><tbody><tr><td colspan="2">In-Plant DSA and Visual Welding Inspection Services</td></tr><tr><td>(1) 180 x 72'6" Building A</td><td>\$45,600.00 per building</td></tr><tr><td>(1) 144 x 72'6" Building B</td><td><u>\$36,000.00</u> per building</td></tr><tr><td>Estimated Total:</td><td><u>\$81,600.00</u> (not to exceed)</td></tr></tbody></table>	<u>No. & Size of Buildings</u>	<u>Inspection Rate</u>	In-Plant DSA and Visual Welding Inspection Services		(1) 180 x 72'6" Building A	\$45,600.00 per building	(1) 144 x 72'6" Building B	<u>\$36,000.00</u> per building	Estimated Total:	<u>\$81,600.00</u> (not to exceed)
<u>No. & Size of Buildings</u>	<u>Inspection Rate</u>									
In-Plant DSA and Visual Welding Inspection Services										
(1) 180 x 72'6" Building A	\$45,600.00 per building									
(1) 144 x 72'6" Building B	<u>\$36,000.00</u> per building									
Estimated Total:	<u>\$81,600.00</u> (not to exceed)									

Any required material testing must be provided by a DSA approved lab (not affiliated with the in-plant IOR)

Respectfully Submitting,

Stacey Douglas

Accepted by:	Date: / /
--------------	-----------